

Work Order ID 70641

Monday, June 20, 2011 8:15:06 AM



Page 1

Item ID: D412-742-013

Accept



Setup Start



Revision ID:

Item Name: Float Skidtube Installation

Stop



Start Date: 6/10/2011 Start Qty: 1.00



Cust Item ID:

DUPLICATE

Required Date: 6/30/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals: Process Plan: mf

Date: 11-06-20

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

| Draw Nbr | Revision Nbr |
|--------------|--------------|
| IIN D412-742 | D |

100

0.00



DOCUMENT CONTROL

DC

Memo

0.00

Document Control

Photocopy bluefile and create labels per PPP D412-742-013

CHG006

8/16/30

11/6/20 BG 11-6-20

110

Pick Kit

0.00



Packaging

Memo

0.00

Packaging

11/6/21

120

QC4- 100% Inspect kits for completeness

0.00



QC

Memo

0.00

Quality Control

8/16/30

70

Work Order ID 70641

Monday, June 20, 2011 8:15:06 AM

Page 2

Item ID: D412-742-013

Accept

Setup Start

Revision ID:

Stop

Item Name: Float Skidtube Installation

Start Date: 6/10/2011 Start Qty: 1.00

Cust Item ID:

Required Date: 6/30/2011 Req'd Qty: 1.00

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130



Packaging

Packaging

0.00

Memo

0.00

Identify and pack for shipping as per PPP D412-742-013
Location:

NEU

140



QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

6/30/30

11/6/30

11/10/30

Monday, June 20, 2011 8:15:01 AM

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

2. Once the problem is identified, the next step is to define the objectives and goals of the project. This helps to clarify what needs to be achieved and provides a clear direction for the team.

3. The third step is to develop a plan or strategy to address the problem. This involves breaking down the problem into smaller, manageable tasks and determining the resources needed to complete each task.





4. The fourth step is to implement the plan. This involves putting the strategy into action and monitoring progress regularly to ensure that the project is on track.

5. The final step is to evaluate the results of the project. This involves comparing the actual outcomes with the objectives and goals to determine the effectiveness of the project and identify areas for improvement.

Required Date: 6/30/2011

Required Qty: 1.00

Comments: IPP Rev: A 05.10.13 New Issue KJ/JLM
 IPP Rev:B 06-06-08 As per DS19336 JLM IPP RevC 07-12-03 ECN
 1072 DD verified by:JLM
 IPP Rev:D 08-09-08 ecn 08-510 DD verified by:EC
 IPP Rev:E 09-01-23 as per DS19441 DD verified by:EC IPP RevF: add
 AN4C7A DD 10.01.13 verified by:EC

| Component Item ID/ Item Name | Replacement Item ID | Mfg/ Purch | Bin Item | Primary Location | Last Location | Route Seq ID | Unit of Measure | Qty on Hand | Qty per Kit | Total Qty | Qty Issued | Date Issued | Status |
|---|------------------------|---------------|-------------|---------------------|------------------|-----------------|--------------------|----------------|-------------|-----------------|---------------|----------------|--------|
| AN4C7A  | | Purchased | No | | | 110 | Each | 367.0000 | 4 | 4 | | | |
| Bolt | | | | | | | | | | | | | |
| | | | | <u>Location</u> | | | | <u>Loc Qty</u> | | <u>Loc Code</u> | | | |
| | | | | ST356 | | | | 367 | | | | | |
| | | | | 109147 | | | | 367 | | | | | |
| D412-742-043  | | Manufactured | No | | | 110 | Each | 0.0000 | 1 | 1 | | | |
| Replacement Float Skidtube | | | | | | | | | | | | | |
| D2571  | | Manufactured | No | | | 110 | Each | 4.0000 | 1 | 1 | | | |
| Saddle, Fwd Out 205 | | | | | | | | | | | | | |
| | | | | <u>Location</u> | | | | <u>Loc Qty</u> | | <u>Loc Code</u> | | | |
| | | | | ST434 | | | | 4 | | | | | |
| | | | | 69698 | | | | 4 | | | | | |
| D2572  | | Manufactured | No | | | 110 | Each | 1.0000 | 1 | 1 | | | |
| Saddle, Fwd In 205 | | | | | | | | | | | | | |
| | | | | <u>Location</u> | | | | <u>Loc Qty</u> | | <u>Loc Code</u> | | | |
| | | | | ST434 | | | | 1 | | | | | |
| | | | | 69336 | | | | 1 | | | | | |

| W/O: | | WORK ORDER CHANGES | | | | | |
|------|------|--------------------|----|------|-----|-------------------------------------|--------------------------|
| DATE | STEP | PROCEDURE CHANGE | By | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | | | | | | | |
| | | | | | | | |

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

| NCR: | | WORK ORDER NON-CONFORMANCE (NCR) | | | | | | |
|------|------|----------------------------------|-----------------------------|---------------------------------|----------------|---------------------------|-----------------------|--------------------------|
| DATE | STEP | Description of NC Section A | Corrective Action Section B | | | Verification Section C | Approval Chief Eng | Approval QC Inspector |
| | | | Initial Chief Eng | Action Description Chief Eng | Sign & Date | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

NOTE: Date & initial all entries

Picklist Print

Monday, June 20, 2011 8:15:02 AM

Page 2

Work Order ID: 70641

Parent Item: D412-742-013

Parent Item Name: Float Skidtube Installation

Start Date: 6/10/2011

Required Date: 6/30/2011

Start Qty: 1.00

Required Qty: 1.00

D2573

Manufactured No

110 Each

2.0000



Saddle, Aft Out 205



1 1
B 70458

Location

Loc Qty

Loc Code

ST434

2

69697

2

D2574

Manufactured No

110 Each

2.0000



Saddle, Aft In 205



1 1
B 70459 11/6/22

Location

Loc Qty

Loc Code

ST434

2

69699

2

D2876

Manufactured No

110 Each

52.0000



Saddle Spacer



2
a

Location

Loc Qty

Loc Code

ST025

16

66849

16

ST026

36

68282

36

D2877

Manufactured No

110 Each

71.0000



Saddle Spacer



2 2
11/6/15

Location

Loc Qty

Loc Code

ST025

71

66843

21

68283

50

o

| W/O: | | WORK ORDER CHANGES | | | | | |
|------|------|--------------------|----|------|-----|-------------------------------------|--------------------------|
| DATE | STEP | PROCEDURE CHANGE | By | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | | | | | | | |
| | | | | | | | |

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

| NCR: | | WORK ORDER NON-CONFORMANCE (NCR) | | | | | | |
|------|------|----------------------------------|-----------------------------|---------------------------------|----------------|---------------------------|-----------------------|--------------------------|
| DATE | STEP | Description of NC Section A | Corrective Action Section B | | | Verification Section C | Approval Chief Eng | Approval QC Inspector |
| | | | Initial Chief Eng | Action Description Chief Eng | Sign & Date | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

NOTE: Date & initial all entries

Picklist Print

Monday, June 20, 2011 8:15:02 AM

Page 3

Work Order ID: 70641



Parent Item: D412-742-013



Parent Item Name: Float Skidtube Installation

Start Date: 6/10/2011

Required Date: 6/30/2011

Start Qty: 1.00

Required Qty: 1.00

8

D3403-1



Bushing

Manufactured No

110 Each

77.0000

16 16



SL

Location

Loc Qty

Loc Code

ST052

77

69508

37

70696

40

16

D2747



Set Screw

Manufactured No

110 Each

130.0000

4 4



SL

Location

Loc Qty

Loc Code

ST021

130

64276

30

69494

100

4

D3533-1



Set Screw

Manufactured No

110 Each

86.0000

2 2



11/6/11 SL

Location

Loc Qty

Loc Code

ST066

86

67583

86

2

| W/O: | | WORK ORDER CHANGES | | | | | |
|------|------|--------------------|----|------|-----|-------------------------------------|--------------------------|
| DATE | STEP | PROCEDURE CHANGE | By | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | | | | | | | |
| | | | | | | | |

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

| NCR: | | WORK ORDER NON-CONFORMANCE (NCR) | | | | | | |
|------|------|----------------------------------|-----------------------------|---------------------------------|----------------|---------------------------|-----------------------|--------------------------|
| DATE | STEP | Description of NC Section A | Corrective Action Section B | | | Verification Section C | Approval Chief Eng | Approval QC Inspector |
| | | | Initial Chief Eng | Action Description Chief Eng | Sign & Date | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

NOTE: Date & initial all entries

Picklist Print

Monday, June 20, 2011 8:15:02 AM

Page 4

Work Order ID: 70641

Parent Item: D412-742-013

Parent Item Name: Float Skidtube Installation

Start Date: 6/10/2011

Required Date: 6/30/2011

Start Qty: 1.00

Required Qty: 1.00

AN4C6A

Purchased

No

110

Each

340.0000

16

16



Bolt

Location

Loc Qty

Loc Code

FG

4

103344

4

ST306

44

117313

44

ST356

292

116704

17

117619

150

117794

50

117872

75

AN4C52A

Purchased

No

110

Each

107.0000

8

8



BOLT

Location

Loc Qty

Loc Code

ST361

107

117163

60

117619

8

117688

14

118012

25

AN6C12A

Purchased

No

110

Each

62.0000

8

8



BOLT

Location

Loc Qty

Loc Code

ST342

62

116022

8

117688

54

Monday, June 20, 2011 8:15:02 AM

Shop Packet Print

Page 4

| W/O: | | WORK ORDER CHANGES | | | | | |
|------|------|--------------------|----|------|-----|-------------------------------------|--------------------------|
| DATE | STEP | PROCEDURE CHANGE | By | Date | Qty | Approval Chief Eng / Prod Mgr | Approval QC Inspector |
| | | | | | | | |
| | | | | | | | |

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

| NCR: | | WORK ORDER NON-CONFORMANCE (NCR) | | | | | | |
|------|------|----------------------------------|-----------------------------|---------------------------------|----------------|---------------------------|-----------------------|--------------------------|
| DATE | STEP | Description of NC Section A | Corrective Action Section B | | | Verification Section C | Approval Chief Eng | Approval QC Inspector |
| | | | Initial Chief Eng | Action Description Chief Eng | Sign & Date | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

NOTE: Date & initial all entries

Picklist Print

Monday, June 20, 2011 8:15:02 AM

Page 5

Work Order ID: 70641

Parent Item: D412-742-013

Parent Item Name: Float Skidtube Installation

Start Date: 6/10/2011

Required Date: 6/30/2011

Start Qty: 1.00

Required Qty: 1.00

D3672-3 Manufactured No

110 Each

359.0000

32 32



Phenolic Washer

Location

Loc Qty

Loc Code

ST074

359

64176

359

AN960C416L

Purchased No

110 Each

0.0000

32 32



WASHER

D3672-9

Manufactured No

110 Each

328.0000

8



Phenolic Washer

Location

Loc Qty

Loc Code

ST074

328

35523

328

AN960C616L

Purchased No

110 Each

4.0000

8



WASHER

Location

Loc Qty

Loc Code

ST347

4

113064

4

D3672-11

Manufactured No

110 Each

411.0000

16



Phenolic Washer

Location

Loc Qty

Loc Code

ST074

411

58046

411

Monday, June 20, 2011 8:15:02 AM

Shop Packet Print

Page 5

Picklist Print

Monday, June 20, 2011 8:15:02 AM

Page 6

Work Order ID: 70641

Parent Item: D412-742-013

Parent Item Name: Float Skidtube Installation

Start Date: 6/10/2011

Required Date: 6/30/2011

Start Qty: 1.00

Required Qty: 1.00

MS21043-4 Purchased No 110 Each 1,111.000 29 29
Nut

| Location | Loc Qty | Loc Code |
|----------|---------|----------|
| FG | 40 | |
| 104603 | 40 | |
| ST300 | 71 | |
| 117423 | 71 | |
| ST301 | 1000 | |
| 117601 | 500 | |
| 117793 | 500 | |

D3403-3 Manufactured No 110 Each 61.0000 8 8
Bushing

| Location | Loc Qty | Loc Code |
|----------|---------|----------|
| ST | 61 | |
| 69509 | 61 | |

D3405-041 Manufactured No 110 Each 2.0000 1 1
Lug Assembly

| Location | Loc Qty | Loc Code |
|----------|---------|----------|
| ST474 | 2 | |
| 62227 | 2 | |

D3405-043 Manufactured No 110 Each 6.0000 1 1
Lug Assembly

| Location | Loc Qty | Loc Code |
|----------|---------|----------|
| ST423 | 2 | |
| 65703 | 2 | |
| ST474 | 4 | |
| 68343 | 4 | |

Monday, June 20, 2011 8:15:02 AM

Shop Packet Print

Page 6

Picklist Print

Monday, June 20, 2011 8:15:02 AM

Page 7

Work Order ID: 70641

Parent Item: D412-742-013

Parent Item Name: Float Skidtube Installation

Start Date: 6/10/2011

Required Date: 6/30/2011

Start Qty: 1.00

Required Qty: 1.00

AN4C47A

Purchased

No

110

Each

55.0000



Bolt



4

4

Location

Loc Qty

Loc Code

ST361

55

117163

40

117619

15

Manufactured

No

110

Each

0.0000

D3407-041



Tow Ring



1

1

D3417-3

Manufactured

No

110

Each

84.0000



Washer



2

2

Location

Loc Qty

Loc Code

FG

9

33519

9

ST053

75

51648

28

53182

23

66847

24

Manufactured

No

110

Each

48.0000

D3456-1



Washer



1

1

Location

Loc Qty

Loc Code

FG

7

25701

7

ST054

41

66848

3

69774

38

Monday, June 20, 2011 8:15:03 AM

Shop Packet Print

Page 7

Picklist Print

Monday, June 20, 2011 8:15:03 AM

Page 8

Work Order ID: 70641

Parent Item: D412-742-013

Parent Item Name: Float Skidtube Installation

Start Date: 6/10/2011

Required Date: 6/30/2011

Start Qty: 1.00

Required Qty: 1.00

AN3C37A

Purchased

No

110

Each

125.0000



BOLT



1

1

Location

Loc Qty

Loc Code

ST353

98

116874

11

117010

2

117763

25

117885

60

ST354

27

117343

27

AN3C40A

Purchased

No

110

Each

87.0000



BOLT



1

1

Location

Loc Qty

Loc Code

ST354

87

112454

37

114442

50

AN3C41A

Purchased

No

110

Each

161.0000



BOLT



1

1

Location

Loc Qty

Loc Code

FG

4

103324

4

ST354

157

117163

2

117407

80

117950

75

Monday, June 20, 2011 8:15:03 AM

Shop Packet Print

Page 8

Picklist Print

Monday, June 20, 2011 8:15:03 AM

Page 9

Work Order ID: 70641

Parent Item: D412-742-013

Parent Item Name: Float Skidtube Installation

Start Date: 6/10/2011

Required Date: 6/30/2011

Start Qty: 1.00

Required Qty: 1.00

AN3C42A

Purchased

No

110

Each

43.0000



BOLT



1

Location

Loc Qty

Loc Code

ST354

43

106176

23

117763

20

AN3C43A

Purchased

No

110

Each

59.0000



BOLT



4

Location

Loc Qty

Loc Code

ST354

34

114455

20

117313

14

ST355

25

117688

25

AN3C46A

Purchased

No

110

Each

42.0000



BOLT



5

Location

Loc Qty

Loc Code

FP-B

17

113302

17

ST355

25

117764

25

AN960C10L

NAS1149C0332

Purchased

No

110

Each

0.0000

R



washer



26

26

117764 11/6/21

Monday, June 20, 2011 8:15:03 AM

Shop Packet Print

Page 9

Picklist Print

Monday, June 20, 2011 8:15:03 AM

Page 10

Work Order ID: 70641



Parent Item: D412-742-013



Parent Item Name: Float Skidtube Installation

Start Date: 6/10/2011

Required Date: 6/30/2011

Start Qty: 1.00

Required Qty: 1.00

MS21043-3

Purchased

No

110

Each

247.0000

13



Nut



11/6/21

Location

Loc Qty

Loc Code

FG

72

103691

72

ST301

175

112314

175

13

5.2 D412-742-013 (APICAL TRI-BAG) Float Skidtube Installation Parts List

| Item | Qty -013 | Qty -043 | Part Number | Description |
|------|-------------|-------------|-----------------|------------------------------------|
| | X | | D412-742-013 | FLOAT SKIDTUBE INSTALLATION |
| | 1 | X | D412-742-043 | FLOAT SKIDTUBE |
| | | 1 | D3391-043 | 412 FLOAT SKIDTUBE |
| 1 | | *24 | *AN3C4A | *BOLT |
| 3 | | *12 | *AN3C6A | *BOLT |
| 4 | | *8 | *AN3C7A | *BOLT |
| 5 | | *44 | *AN960C10L | *WASHER |
| 21A | | *1 | *D3564-1 | *WEARSHOE (REPLACES D3460-1) |
| 21B | | *1 | *D3566-1 | *GASKET |
| 22A | | *1 | *D3564-3 | *WEARSHOE (REPLACES D3460-3) |
| 22B | | *1 | *D3566-1 | *GASKET |
| 23A | | *1 | *D3564-5 | *WEARSHOE (REPLACES D2577-5) |
| 23B | | *1 | *D3566-5 | *GASKET |
| | | | | |
| 10 | | *1 | *D3391-021 | *412 FORWARD TUBE |
| 11 | | **1 | **D3401-041 | **TOW CAP |
| 12A | | **10 | **AELS-1032-225 | **INSERT (REPLACES NAS1330S3KB166) |
| 12B | | **2 | **AELS-1032-130 | **INSERT (REPLACES NAS1330S3KB166) |
| 13 | | **10 | **AN3C4A | **BOLT |
| 14A | | **4 | **D3672-1 | **WASHER (REPLACES NAS1515H3L) |
| 14B | | **10 | **AN960C10L | **WASHER |
| 24A | | **1 | **D3564-13 | **WEARSHOE |
| 24B | | **1 | **D3566-13 | **GASKET |
| | | | | |
| 20 | | *1 | *D3391-023 | *412 MID TUBE |
| 28 | | **20 | **AELS-1032-130 | **INSERT (REPLACES NAS1330S3KB116) |
| | | | | |
| 30 | | *1 | *D3391-025 | *412 AFT TUBE |
| 25A | | **1 | *D3537-1 | **WEARPAD |
| 25B | | **1 | *D3553-1 | **GASKET |
| 26A | | **1 | *D3537-7 | **WEARPAD |
| 26B | | **1 | *D3553-3 | **GASKET |
| 31 | | **1 | **D2646 | **AFT CAP |
| 32 | | **14 | **AELS-1032-130 | **INSERT |
| 36 | | **12 | **AELS-1032-225 | **INSERT (REPLACES NAS1330S3KB366) |
| 37A | | **6 | **AN3C4A | **BOLT |
| 37B | | **4 | **AN3C5A | **BOLT |
| 38A | | **2 | **D3672-1 | **WASHER (REPLACES NAS1515H3L) |
| 38B | | **10 | **AN960C10L | **WASHER |

(CONTINUED ON PAGE 19)

(CONTINUED FROM PAGE 18)

| Item | Qty -013 | Qty -043 | Part Number | Description |
|------|-------------|-------------|-------------|------------------------------|
| 40 | 1 | | D2571 | SADDLE, FWD OUTSIDE |
| 41 | 1 | | D2572 | SADDLE, FWD INSIDE |
| 42 | 1 | | D2573 | SADDLE, AFT OUTSIDE |
| 43 | 1 | | D2574 | SADDLE, AFT INSIDE |
| 44 | 2 | | D2876 | SADDLE SPACER |
| 45 | 2 | | D2877 | SADDLE SPACER |
| 46 | 16 | | D3403-1 | BUSHING |
| 47A | 4 | | D2747 | SET SCREW |
| 47B | 2 | | D3533-1 | SET SCREW |
| 48 | 16 | | AN4C6A | BOLT |
| 49 | 8 | | AN4C52A | BOLT |
| 50 | 8 | | AN6C12A | BOLT |
| 51A | 32 | | D3672-3 | WASHER (REPLACES NAS1515H4L) |
| 51B | 32 | | AN960C416L | WASHER |
| 52A | 8 | | D3672-9 | WASHER (REPLACES NAS1515H6L) |
| 52B | 8 | | AN960C616L | WASHER |
| 53 | 16 | | D3672-11 | WASHER (REPLACES NAS1515H7L) |
| 54 | 24 | | MS21043-4 | NUT |
| 55 | 4 | | ANC47A | BOLT |
| 60 | 8 | | D3403-3 | BUSHING |
| 61 | 1 | | D3405-041 | GHW LUG |
| 62 | 1 | | D3405-043 | GHW LUG |
| 63 | 4 | | AN4C46A | BOLT |
| 64 | 4 | | MS21043-4 | NUT |
| 70 | 1 | | D3407-041 | TOW RING |
| 71 | 2 | | D3417-3 | WASHER |
| 72 | 1 | | MS21043-4 | NUT |
| 73 | 1 | | D3456-1 | WASHER |
| 91 | 1 | | AN3C37A | BOLT |
| 92 | 1 | | AN3C40A | BOLT |
| 93 | 1 | | AN3C41A | BOLT |
| 94 | 1 | | AN3C42A | BOLT |
| 95 | 4 | | AN3C43A | BOLT |
| 97 | 5 | | AN3C46A | BOLT |
| 99 | 26 | | AN960C10L | WASHER |
| 100 | 13 | | MS21043-3 | NUT |

*DENOTES PART IS INCLUDED WITH D3391-043 ASSEMBLY ABOVE

**DENOTES THAT PART IS INCLUDED WITH ASSEMBLY ABOVE

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS IIN-D412-742 REV. D AND
INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA-D412-742 REV. 3.

REF. FAA STC: SR01583SE
REF. CANADIAN STC: SH05-37
REF. EASA STC: EASA.IM.R.S.01126

INSTRUCTIONS: REFERENCE ONLY

1) FOR D412-742-011/-013 SKIDTUBES @ CHANGE 006 AND SUBSEQUENT, UPDATE THE PARTS LIST TO MODIFY THE BOLT USED TO ATTACH THE GHW LUG AS FOLLOWS:

5.1 D412-742-011 (PMA/OEM) Float Skidtube Installation Parts List

32.15 D412-742-011 (PMA/OEM) Float Skidtube Installation Parts List

| ITEM | Qty -011 | Qty -041 | Qty -015 | PART NUMBER | DESCRIPTION |
|------|-------------|-------------|-------------|--------------|-----------------------------|
| | X | | | D412-742-011 | FLOAT SKIDTUBE INSTALLATION |
| | 1 | X | | D412-742-041 | FLOAT SKIDTUBE |
| | 1 | | X | D412-742-015 | ELECTRIC STEP KIT |

IS:

| | | | | | |
|----|---|--|--|---------|------|
| 63 | 4 | | | AN4C47A | BOLT |
|----|---|--|--|---------|------|

WAS:

| | | | | | |
|----|---|--|--|---------|------|
| 63 | 4 | | | AN4C46A | BOLT |
|----|---|--|--|---------|------|

5.2 D412-742-013 (APICAL TRI-BAG) Float Skidtube Installation Parts List

32.16 D412-742-013 (APICAL TRI-BAG) Float Skidtube Installation Parts List



| ITEM | Qty -013 | Qty 043 | PART NUMBER | DESCRIPTION |
|------|-------------|------------|--------------|-----------------------------|
| | X | | D412-742-013 | FLOAT SKIDTUBE INSTALLATION |
| | 1 | X | D412-742-043 | FLOAT SKIDTUBE |

IS:

| | | | | |
|----|---|--|---------|------|
| 63 | 4 | | AN4C47A | BOLT |
|----|---|--|---------|------|

WAS:

| | | | | |
|----|---|--|---------|------|
| 63 | 4 | | AN4C46A | BOLT |
|----|---|--|---------|------|

| | | | |
|------------|---|---|----------|
| A | NEW ISSUE | AJS | 08.12.19 |
| REV. | DESCRIPTION | BY | DATE |
| DESIGN | AJS | DART AEROSPACE USA, INC PORT HADLOCK, WA | |
| DRAWN | AJS | | |
| CHECKED |  | REV. A SHEET 1 OF 1 | |
| MFG. APPR. | N/A | | |
| APPROVED |  | SCALE NTS | |
| DE APPR. | | | |
| DATE | 08.12.19 | COPYRIGHT © 2008 BY DART AEROSPACE USA, INC <small>THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.</small> | |